

Bulletin Date:	06.April.2015		
Models Affected:	Assault AirBike / AAB	Posted By:	Skip Reys
Short Description:	A step-by-step guide to reinforce the importance of the proper assembly of the linkage/lower handlebar pivot.		

Symptom

Incorrect assembly can deform the seals, causing damage to the bearings and failure.

Cause

Incorrect assembly

Solution

Follow the correct assembly instructions to ensure proper function and service life.

Fig. 1

Process

Step 1 : Read the entire Technical Service Bulletin

Step 2 : Remove the

ONLINE RESOURCES

Assault Fitness YouTube Channel:

www.youtube.com/user/AssaultAirBike



Bike Assembly Video:

<https://youtu.be/-BHICcd7NB8>



Bike Routine Maintenance Video:

https://youtu.be/_Gi7qSORmwc



Service Information:

www.assaultfitnessproducts.com/support/warranty.html

